Notice of Completion

extense from these Two Pulse let Dost Collectors that not exceed 0.000 granufact over 3.24

WARNING

Regulation I, Section 6.09, requires that the owner or applicant notify the Agency of the completion of the work covered by the application and when its operation will begin. This form is provided for your convenience to assist you in complying with this part of the Regulation.

APPLICANT o	r OWNER SECTION) स ^र
Mail to:	Puget Sound Clean Air Agency	* * * * * * * * * * * * * * * * * * *	t = 1	
TALL TO.	Plan Review Section	1	T. Carlotte and Car	
	110 Union Street, Suite 500		,	
	Scattle, Washington 98101-2038	11 25 100 2 12 1		
	Beatte, Washington 70101-2030	ages 1, 20th	y .	٠.,
Gentlemen:		,		٠, ،
The project desp	ntbed below was completed on <u>Mar</u>	ch 25 2002		
		1 0/1 6	-	-11
Cal	Line .	Mer Safety+ in	206694-6221	3/25/0~
Signatu:	re of Owner and/or Applicant	Title	Phone	Dete
FOR AGENCY	USE ONLY		Notice of Construction 1	No. 864 3
* .			Registration No.	11339
Project Descripti	ion	¥	-	
Two Pulse J	et Dust Collector Conversions (64 Filters	@ 41.5"x6.13" each, @2.26 c	fm/ft2) and Fans rated at 420	0
CFM each to	o convert existing Sly Dust Collectors on (Group II Cement Silos		
di .				Conditions on
Applicant	os.	Owner ·		Reverse Side
Henrik Vold	lbaek			
Ash Grove Cement Company (E Marginal) 3801 E Marginal Way S Seattle, WA, 98134-1113		Ash Grove Cement Company (E Marginal) 3801 E Marginal Way S		
		Location		a
Ash Crove (Cement Company (E Marginal), 3801 E M	Jorginal Way C Scottle WA	00124	
		larginal way o, ocatic, was	20134 ,	
	Inspector Check Engine	eer FLA	and Inspector check.	,
Follow up	<u></u>	(Estimated	completion date plus 7)	
Date Inspected		Inspector		
Remarks			15.21 B	
		0.0		
				15-43
				30/ 53/
				- T
COMPRESSOR				
COMPLETONS				
Form 68-01-0-75/981	对于大型的工作,但是一种企业的工作。	(A) 是 15 (A)	DOLLARDON SERVICE TO THE SERVICE SERVI	是被提出的。这一

AGCS2M002373